

COPY

Ship's name "AFRICAN REEFER" Port B.As No. 34904

Class is subject to

Last survey date 11.3.63

- 1) Starboard aft auxiliary engine entablature (Metalocked in way of No. 3 cylinder) being specially examined by 9.63.
- 2) Main standby cooling pump (Metalocked) being examined by 9.63.
- 3) Starboard aft auxiliary engine (Metalocked^{11/62} in way of No. 1 cylinder) being specially examined by 5.63.

Repairs

Metalock repairs and strpa reinforcements of two small fractures in way of top flange of main engine No. 2 cylinder aft port column. Surveyor recommends main engine No. 2 cylinder after port column (metalocked) 3/63 at the top flange being again examined by September 1963.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as above and as now recommended.



© 2020

Lloyd's Register
Foundation