

THROUGH COPENHAGEN
COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

14th December, 1962.

Dear Sirs,

M.S. "AFRICAN REEFER".

C.
DNS/BN

Further to my letter of the 15th November last, I have to inform you that the report has now been received from the Society's Littleton Surveyors in respect of damage found to the No.1 cylinder of the starboard aft auxiliary engine.

Repairs were carried out by the Metalock process, and the Committee have continued the class subject, inter alia, to the starboard aft auxiliary engine in way of No.1 cylinder (Metalock repairs) being specially examined by the end of May 1963.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

Messrs. J. Lauritzen,
Hammerensgade 1,
Copenhagen K,
DENMARK.



© 2020

Lloyd's Register
Foundation

003245-003251-0076