

THROUGH COPENHAGEN

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

15th November, 1962.

C

Dear Sirs,

MWK/HJW

Motorship "AFRICAN REEFER"

A report of a survey carried out at Lyttelton on the 27th September has now received the consideration of the Committee, and at this time the Metalock repairs to the starboard aft auxiliary engine entablature in way of No.3 cylinder, and the main standby cooling pump were again examined and found to remain efficient meantime.

It was recommended, however, that these repairs be again examined and dealt with as necessary before the end of September, 1963 and the Committee have continued the class subject to these items receiving attention by the time stated.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

Messrs. J. Lauritzen,
Hammerensgade 1,
COPENHAGEN K.
Denmark.



© 2020

Lloyd's Register
Foundation

003245-003251-0079