

Ship's name "AFRICAN REEFER" Survey port Lyt. No. 5090
B
ass is subject to NONE. Last survey date 14.10.61.

16 NOV 1961

L. Appendix. (As before ~~otherwise~~)
ture of present survey (afloat and in drydock)

Minor repairs.

commendation

SUBMITTED record of +DS 10,61' be assigned
as recommended.

DS 10,61.

IN S.R.L. APPENDIX.

Midship deckhouse bulkhead (p.s.) set in.



© 2020

Lloyd's Register
Foundation

003245-003251-0080

2.11.61.