

# LLOYD'S REGISTER OF SHIPPING

## RECEIVED

8 JAN 1959

95, Bothwell Street, Glasgow, C.2

Telegrams: Register, Glasgow

7th January, 1959.

Telephone: Central 6491 (4 Lines)

Ans d.....

Dear Sir,

Steamer "EMPIRE SHEARWATER"

In reply to your letter of the 2nd instant regarding Glasgow Report No. 89407, the Surveyors confirm that items 1, 3, 5, 6 and 7 in the Rpt. 9 have been complied with.

The Surveyors also state that the thickness of .21" entered in the drilling sheet for the 1st strake inboard starboard forward is in error, and should have been .23" as obtained from further drilling. *Ref*

With regard to the remaining thicknesses in question it is confirmed that these reductions were local and are not indicative of the general thicknesses of the plating as this ship has been well maintained, but it is agreed that additional drillings should have been taken. *Ref*

The overall length also requires to be amended to 342'-6", but in this respect attention is drawn to the overall dimension of 330'-0" at present recorded in the Register Book. *Ref*

These discrepancies are regretted, and it will be appreciated if the necessary amendments can be made accordingly. *Ref*


Yours faithfully,

*W. Stewart*

Secretary to the  
Scottish Committee.

*copy  
19/12.*

The Secretary,  
LONDON.



Lloyd's Register  
Foundation

003245-003251-0151



CLASSIFICATION

H ~~DM~~  
C

Raf

NOTED FOR  
POSTING

amended O.L. for R.B. RSP 9/1/59

9/1/58

initial  
c. Sept 15



© 2020  
Lloyd's Register  
Foundation

RECEIVED

RECEIVED 2 REGISTER OF SHIPPING

82, Borthwell Street, Glasgow, C.2

14th January, 1959

14th January 1959 (17.1.59)