

SECTION

714

003275-003281-0005

Received for

SHIP'S NAME "NISO".

DW

Outstanding Conditions of Class: NONE.

Endorsement of Certificate (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Drydocking. Temporary and deferred repairs to extensively fractured stern frame side and sole piece, twisted rudder stock and fractured rudder carrier and gland on account of grounding damage.

Recommendation:

SUBJECT to twisted rudder stock, fractured rudder carrier and part rudder plating being renewed and to fractured stern frame being part renewed before the ship is recommissioned but further ACTION be DEFERRED repairs. The Newcastle Surveyor above temporary repairs in view to enable the water for laying

*Mr. K. B. Blackwater.
29/6 - laid up.*

Subject.

S.R.L. APPENDIX.

Indents in stem, bottom and etc. (p & s). ~~...~~

Blk(new)



© 2020

Lloyd's Register
Foundation