

17th July, 1959.

COLOMBO

4425, 27, 28, 35, 40 - As recommended.

4433 "KING WILLIAM" As recommended, except that the class has been continued free of conditions regarding the machinery.

In this connection I have to inform you that you are not in order in recommending that the class be continued subject to machinery spare parts being placed on board, as replacement of such items is the Owners' responsibility.



© 2020

Lloyd's Register
Foundation

003275-003281-0080