

000

COMMITTEE LON

PO C AND J 010

TX 1343 TH +UZA350 THREE 21 13 1045 VIA C AND W =

ELT = COMMITTEE TELEX LONDON =

KYPROS OWNERS WISH TO SAIL VESSEL TO SPLIT ~~FOR REPAIRS~~

FOR BREAKING UP STOP PLEASE INSTRUCT MINIMUM REQUIREMENTS =

REGISTER +

SENT 1213TH QMC 010

PO C AND W

COMMITTEE LON

CABLE IN


15 AUG 1960

825
984
Perf
25

RECEIVED

15 AUG 1960

AND



© 2020

Lloyd's Register
Foundation

VMX

003282-003289-0013

ey(s) and/or conditions

MAS 12 58

SR ER

CLASSIFICATION

H

Submitted ~~M~~ certificate
might be issued as desired
is found or placed in satisfactory
condition for the voyage imposed as per
unclassified ship. (Refer. P. Rpt. no. 7775)
15/8/60

If boiler not steamed since
June 1959. Generally examine
boiler internally, open out and examine
safety valves and complete MB's as
per Rpt 8064. Carry out short
sea trial to ensure navigability
and that sea valves are not choked.
Examine windlass cylinder
(condition of class)
15/8/60



© 2020

Lloyd's Register
Foundation