

## LLOYD'S REGISTER OF SHIPPING

Port Karachi,26th October, 1901

This is to Certify that I have

Part  
 Surveyed the Machinery of the S.S. "FAUSTA", 6460 tons gross of  
 Karachi, whilst in drydock and afloat on the 12th September,  
 1901 and subsequently, for Main Boiler Survey and General  
 Examination,  
 and that I will transmit to the Committee of Lloyd's Register of  
 Shipping, London, a Report stating that all recommendations made by  
 me in connection therewith have been carried out to my satisfaction; also  
 that I will Recommend that in the case of this Vessel the following  
 Survey Records be made in the Supplement to the Register Book

M.B.S. 10,01

and that her Machinery Classification Record be continued in the Book,  
 subject to the main sea water circulating pump impeller and  
 shaft being renewed by the end of February 1902 (four months  
 limit), but without condition concerning the main engine  
 turning gear.

Parts now examined:

(C.S. Items only)

(T.L. Palmer)

  
 Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
 to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held  
 responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
 other than a declaration of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
 the Surveyors, or other Officers or Agents of the Society."

© 2020

Lloyd's Register  
Foundation

003282-003289-0108