

Received from Chief Ship Surveyor

13 JUN 1961

SHIP'S NAME "HETTON BANK" REPORT SYD. No. 33935

Outstanding Conditions of Class:

'B' & 'C' strakes (p.s.) with as necessary by the Special Survey. SUBJECT to scrubbed bottom shell plating being specially examined and dealt

S.R.L. Appendix. (~~As before~~ or None)

Signature of Present Survey: (Afloat and ~~in dry dock~~)

Examination afloat on account of striking submerged object.

Recommendation:

SUBJECT as above, but further ACTION be DEFERRED for examination in dry dock after striking submerged object.

SUBJECT.

INSERT IN S.R.L.
Drydocking(grounding).

W.S.I.
1-6.61



© 2020

Lloyd's Register
Foundation