

EXTRACT FROM ENGINE ROOM LOG BOOK OF  
S.S. "FORT ORLEANS".

Saturday, 27th November, 1943.

8:15 P.M. Whilst changing Feed Water Grease Extractor,  
outboard valve jammed.

On examination found seat out of position, bent  
and broken.

8:40 P.M. Master decided to return to port for repairs.

Sunday, 28th November, 1943.

Anchored 12:32 A.M. F.W.E. 12:42 A.M.

(Sgd.) J. E. Young  
Chief Engineer.



© 2020

Lloyd's Register  
Foundation

003242-003289-0183