

Received from Chief Ship Surveyor

27 APR 1960

SHIP'S NAME "TECTUS" REPORT Rot. No. 49186
GB

Outstanding Conditions of Class: SUBJECT to indented shell plates
Nos. 5 & 6 in 2nd below and No.5 in 3rd below sheer (p.s.a) being
dealt with at the Special Survey.

S.R.L. Appendix. ~~(As before or None)~~

Nature of Present Survey: ~~(At float and in dry dock)~~

E.W.repairs to sternframe solepiece:
Deferred repairs to indented shell plating.

Recommendation:

SUBMITTED record of 'DS 3,60' be assigned
as recommended, subject to sternframe (E,W 3,60)
being specially examined at the next drydocking
and to indented shell plating (p & s) being
specially examined and dealt with as necessary
at the Special Survey but without other condition.

DS 3,60 Subject
Without.

Blk (new)

C.S.S. Records Dept.
to note.

© 2020



Lloyds Register
Foundation

003290-003297-0011