

REPAIRS, OR EXAMINATIONS PER ROLL, FOR
Vessel afloat. Both lower masts were now renewed.

2m, 9.47.

FREEBOARD REPORT on the

Kragujevac

The ship's Surveyor reported on 30.8.48
that 49 new hatch covers were fitted
on board at Rijeka on 24.8.48

Mr Turnbull
Reports Dept

87
10.48



Lloyd's Register
Foundation

003290 - 003291 - 0223

The Builders shall be obliged for any remark which could
be made in connection with the construction, as they intend to
apply this system of manufacture for all future orders.

mean diamr.
on board.)
length size