

Ship's name "ESSO KOBENHAVN" Port CPN. No. 20270
17.4.63.

The class is subject to fractured bottom plate in way of No.9 cargo tank (p.s) and bottom shell plating in No.7 main tank (p.s) to fractured bilge plate L.11 and rivets in way of bottom longitudinals in way of cement boxes and to fractured side plate K.3 (p.s.f) being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for Special Survey by 3,63, and for Repairs.

A SPECIAL SURVEY (D) became due 10,62. Proposal to postpone the S.S. until 3,63 was previously approved. A further proposal to defer S.S. until 10,63 was approved 15.3.63, provided a satisfactory General Examination is held when the ship is drydocked at Aalborg 3,63. The Copenhagen Surveyors were advised by letter dated 5.4.63 that as this ship would be laid up at Aalborg the Committee were agreeable to class remaining undisturbed in the meantime, provided that all outstanding surveys were dealt with before the ship again proceeds to sea.

The COPENHAGEN Surveyors report (4,63) ship afloat and surveyed prior to being towed to Odense for breaking up.

IT IS SUBMITTED ship is eligible to remain as classed, Subject as above, but further ACTION be DEFERRED for Special Survey also pending further information.

SUBJECT.

IN S.R.L. APPENDIX

(Keep under observation for fractured shell plates).

OBM.
10-5-63



© 2020

Lloyd's Register
Foundation