


26th April, 1962.

1. "BRITAMER." As recommended. It is of course concluded
t the present condition of class relating to the main engine
3 centre guide tube will be dealt with before this vessel
umes service.



© 2020
Lloyd's Register
Foundation

003298-003306-0334