

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

NEWCASTLE-ON-TYNE, No. 113143

Port NEWCASTLE UPON TYNE.

25th January, 1956.

This is to Certify that I have

Donkey  
 Surveyed the Boilers and Machinery of the M.V. "BRITAMER", 9976 tons  
 gross of Oslo, while vessel was lying afloat and in drydock at  
 allsend on the 15th August, 1955 and subsequently, on account of  
 completion of C.S., and for damage stated to have been sustained  
 probably in the heavy weather experienced on voyage from Tampico  
 to New York in December, 1954 when the machinery suffered excessive  
 strain and while crossing outer bar at Caracasibo,  
 and that I have transmitted to the Committee of Lloyd's  
 Register of Shipping, London, a Report stating that all  
 recommendations made by me in connection therewith have  
 been carried out to my satisfaction, and that I have  
 recommended that the record of + LMC. C.S. 1.56, D.B.S. 1.56,  
 P.S. 1.56 and T.S. C.L. 1.56  
 made in the Register Book in the case of this vessel, when  
 the survey has been completed.

Parts now examined:— Propeller, sternbush, screwshaft, sea connections  
 and outside fastenings.  
 in Engine. All cylinders, pistons, rods, valves and gears, side  
 and centre connecting rods, top ends and guides, crankpins and  
 bearings, main bearings and journals. Thrust and intermediate  
 shafts. Attached fuel, L.O., P.W., S.W. and Scavenge Pumps.  
 auxiliaries. Condenser, S.W. circulating, O.F. burning (2),  
 O.F. Transfer and L.O. Pumps, P.W. and L.O. Coolers, O.F.  
 burning Heaters, inboard air compressor, aft main starting air  
 receivers, O.F. service tanks, evaporator, electrical equipment,  
 steam pipes.  
 S.S. Both donkey boilers throughout and safety valves adjusted  
 under steam.

*C. Bell*  
 Engineer Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
 The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed.  
 It is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be  
 held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register  
 of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member  
 of its Surveyors, or other Officers or Agents of the Society."