

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Single Sc.M.V. "BRITAMER"

Report Gls. No. 60852

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

FIRST ENTRY.

When due

2 Longitudinal Bulkheads fitted.

100A1 "Carrying Petroleum in Bulk"

✓ 1 Dk. "Longitudinal framing at bottom and at deck"

✓ Cell.DBuE 73' 171t, DTf 29' 770t, FPT 170t, APT 102t.

✓ FK, 15BH., ~~15BH.~~, Lloyd's A & CP.


✓ P 101', B 35', F 40'.

✓ Machy. aft

O.L. 515'

✓ E.S.D.

30:3:39.



© 2020

Lloyd's Register Foundation

003298-003306-0362