

Sho
Rep
fro

Received from Chief Ship Surveyor

112 MAY 1959

SHIP'S NAME "MATHURA"

REPORT

Sou.

No 25439

GB

Standing Conditions of Class: (s.s) in way of E.R. being specially examined and dealt with as necessary by the S.S., to shell plating in way of propeller lifting eye (p.s.) being further examined and dealt with as found necessary at the next drydocking and to forward bulkhead of deep tank in No.4 hold (wasted & doubled) (s.s.) being permanently repaired next Special Survey also to deep tank not being pressed until repairs have been effected to tank top.

Reformulation of Certificate (~~As before~~ or None)

Location of Present Survey: (Afloat ~~and in dry dock~~)

Wear and tear repairs.

Recommendation:

SUBJECT as above.

As Now. Subject.

The Owners' Representative states that the ship has now been sold to Japanese Owners and renamed "THUMARA" to make one voyage to Japan with cargo and then to be broken up there.

Memo to Parts 7



© 2020

Lloyd's Register
Foundation

Blk(new)

003311-003320-0041

1959 507