

COPY

LLOYD'S REGISTER OF SHIPPING



Port KINGSTON, JAMAICA, B.W.I.

14th July 1959.

This is to Certify that

G. ELLIOTT

the undersigned/^{Acting} Surveyor to this Society did at the request of the Owners, survey the M.P. Slide Valve of the Main Engine of the S.S. "TETELA" 5402 tons of Liverpool, it being reported that, at about 11.00 a.m. on the 13th July 1959, the Slide Valve developed a defect.

For further particulars see Log Books.

On examination at Kingston, Jamaica, B.W.I.,

on the 13th July 1959:

FOUND

One stopper missing, two bolts sheared and two damaged, match box fractured and load spring slack.

RECOMMENDED

Make four new bolts, and repair match box by brazing.

(sgd) G. ELLIOTT.

.....
(Acting) Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."