

Class is subject to the boiler front end plate below the centre furnace being again examined by the end 2. 60.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

23 MAR 1960

SHIP'S NAME "THE DUKE" REPORT NWC No. 116879

Examined when beached
 TS due 2.60 now held.
 MBS due 5.60 now held.

SRL Boiler front end plate examined and defective section of plate now renewed, and other W.T repairs carried out

It is submitted that this vessel is eligible for THE

RECORD.S

TS 3.60
 MBS 3.60

} without subject



© 2020

Lloyd's Register
 Foundation

003311-003320-0201