

18 SEP 1959

Received from Chief Ship Surveyor

NAME "Trochurus"

REPORT *Fal.* No. 13586

Working Conditions of Class:

none.

Appendix. (As before ~~or None~~)

of Present Survey: (~~Afloat and~~ in dry dock)

Drydocking:

Foundation: Submitted record of D.S. 8/59 "be assigned subject to order lower nosing plate, fracture on rudder upper plate (SS), & set-up plating (P. & S) being examined & dealt with as necessary before the ship is service.

159. Subject

from SRH Appendix: Keel plating (P. & S) set-up.



© 2020

Lloyd's Register
Foundation *JH*
16.9.59

003328-003332-0044