

11 APR 1963
Pir. letter of 2.4.63.
PIR. No. 10054Ship's name "ELENI"Port

The class is subject to No 4 plate in 1st strake above sheer (s.s.a) being dealt with as necessary, and to indented sheerstrake and strake below No.3 from forward (s.s) and bilge keel (p.s) being specially examined and dealt with as necessary by the Special Survey.

There is an S.R.L.Appendix item.

"Laid Up - Surveys Overdue 3,60" is recorded in the Register Book.

The Owners were advised that in order to proceed with cargo to Japan as a classed ship, the ship would require to be opened up as for Special Survey and surveyed in dry dock, and repairs limited to those necessary for a Modified S.S. Notation for the period assigned.

The PIRAEUS Surveyors report (2,63) ship examined afloat and in dry dock and a Modified Special Survey carried out. The subject and S.R.L.Appendix items were examined but not dealt with.

In view of the above, IT IS SUBMITTED record of D² 2,63 and Notation of SS (Mod) 2,63 (3 months) be assigned, subject to No.4 plate in 1st strake above sheer (s.s.a) being dealt with as necessary and to indented sheerstrake and strake below No.3 from forward (s.s.) and bilge keel (p.s) being specially examined and dealt with as necessary by the next drydocking.

DS 2,63
SS (Mod) 2,63 (3 months) SUBJECT
AMENDED.

IN S.R.L.APPENDIX.

Bilge plating in way of Nos.6 & 7 cargo oil tanks (p.s) fractured, to be specially examined and reported on next drydocking.

DELETE FROM R.B.

"Laid Up - Surveys Overdue 3,60".

NOTE: It would appear from the Piraeus Surveyors' letter of 2.4.63 that the ship will be scrapped on arrival in Japan.

© 2020

Lloyd's Register
Foundation