

Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

ME

Orion

Rpt.

Runo No. *1421*

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Engine

*Oil Engines 2 SCDA.**6 Cy. 23 $\frac{5}{8}$ " — 43 $\frac{5}{16}$ "**1162 NHP.*

Boilers fitted with forced draught

Main Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
approved type

No main boilers
Yes
No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ LMC 1.36*

2 DB. 171 lb.

The Surveyors should be informed that the test certificates for the electric generators do not appear to have been received.



© 2020

14/1/36.

Lloyd's Register Foundation

003328-003332-0114