



LLOYD'S REGISTER OF SHIPPING

SAFE DEPOSIT CHAMBERS
MCLEOD ROAD

KARACHI

P.O. Box No. 4922
Cablegrams: Lloydreg Karachi

Telephone: 30429

RECEIVED

17th September, 1962.

2 OSEP 1962

C
AH/RW

Ans a

Dear Sir,

s.s. "CHEIKH MARCEL"
Karachi Report No. 3510

In reply to your letter dated 12th instant, we would in the first instance like to state that our recommendation was intended to alter the class from +100A1 to +100A dash.


The undersigned took guidance from the recent case of s.s. "ANWARBAKSH" (see your letter "C" dated 15th June last) where the equipment, although efficient for the service, was considered to be overdue for replacement.

Now understanding that this is not a parallel case, we shall be glad to have your instructions that we may amend our recommendations to read - "subject to a (spare) bower anchor and 15 fathoms of chain being supplied and the underweight untested anchor (supplied KRH 7,62) being renewed all in accordance with Rule requirements at the earliest opportunity.

Yours faithfully,

J. MacLeod
(J. MacLeod.)
For The Surveyors.

The Secretary,
London.



Lloyd's Register
Foundation

003328-003332-0151

42

REPORTS

48

REPORTS

Submitted surveys in
that their amended recommendation
is in order.

[Signature]
2/19/62

© 2020

Lloyd's Register
Foundation