

4 E
16 OCT 1948

Engineer Surveyor

Received from Chief Engineer Surveyor

E "TENAGODUS"

Rpt.

Cff. No. 56166

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
ing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
ated in the endorsement."— Extract from Sub-Committee's Report, 24592.)


~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH-~~

The class is subject to the machinery spare gear being brought up to Rule requirements; the electric fittings in the centre castle 'tween deck space being replaced by fittings of flame proof type and to a spare propeller being supplied.

The Cardiff Surveyors now confirm that the electrical fittings as above, have been dealt with as required and have reported that the spare gear is now in accordance with Rule requirements, except that a spare propeller remains to be supplied.

IT IS SUBMITTED that the vessel's Contemplated Class be made subject to a spare propeller being supplied, but without other special conditions.

For items remaining to complete Classification Survey see endorsement dated 24. 9. 48.



© 2020

Lloyd's Register
Foundation

14. 10. 48.

003328-003332-012