


LLOYD'S REGISTER OF SHIPPING



Port CAPE TOWN

24th October, 1960

This is to Certify that I have

PART starbd boiler
 Surveyed the machinery of the S.S. "THULE" 7481 tons gross of London
 on the 6th October, 1960 and for DAMAGE on the 20th October, 1960
 and subsequently whilst the vessel lay afloat at Cape Town, stated
 to have been caused through negligence on the 20th October, 1960
 at Cape Town,

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
 S.S. (with date) when the survey has been completed,

and that her Machinery Classification Record be continued in the Book
 subject to all outstanding conditions attached to the vessel's
 class being dealt with as previously recommended but without
 special condition regarding the evaporators being repaired.

Parts now examined: for E.S.

(Q.S.X items only)

Port main engine H.P. and I.P. cylinders, covers, pistons,
 piston rods.

Starbd main engine H.P. and I.P. cylinders, covers, pistons,
 piston rods.

(SGD.) D. ROSS INNES

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CS Continuous Survey of Engines
 DBS Donkey Boiler Survey
 ES Engine Special Survey
 MBS Main Boiler Survey
 MES Modified Survey of Oil Engines
 OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
 SPS Steampipe Survey
 TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 While the Committees of the Society use their best endeavours to ensure that the functions of the Society are
 executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any
 liabilities whatever to be held responsible for any inaccuracy in any report or Certificate issued by the Society or its
 Members, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default
 or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.