

003349-003356-0157

"EMPIRE CONFIDENCE"

FOR MR. HECK.

*W.D.B.*  
The dynamo engines described in Report 4c are not the auxiliary engines dealt with in the endorsement dated 3.5.40 and it does **not** appear that these dynamo engines have so far been approved.

*W.D.B.*  
Mr Ritchie should be informed that the scantlings of the crankshaft as shown on Report No 1087/5 (London) 4c meet the requirements of the Rules

*FWJ. 11.6.40*

*3.6.40.*