

COPY

# LLOYD'S REGISTER OF SHIPPING



Port LIVERPOOL.

24th September, 1959.

**This is to Certify that I have**

Part  
Surveyed the Machinery of the m.v. "NICOYA", 3843 gross tons of London  
afloat at Garston,

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will **Recommend** that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book.

Subject to the main circulating water low injection valve chest being  
renewed by 10,59.

Parts now examined:  
(C.S. Items only)

In Engine No.2 Connecting rod, top end and guide.  
Nos.1 and 2 crankpins and bearings.  
Board air compressor.  
Auxiliary air receiver.  
Electrical installation except generators and governors.

*P. H. Ferreri*

Engineer Surveyor to Lloyd's Register  
(P.H.FERRI).

### KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		


This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Form B.1. 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

003357-003368-0011

© 2020



Lloyd's Register  
Foundation