

6- DEC1962

p's name "ARISTOLELES"

Port

Emd.

No. 591

ss is subject to For conditions of class see previous
Last survey date 30.10.62.
endorsement.

L. Appendix (as before ~~xxxxxxx~~)

ure of present survey (afloat ~~xxxxxxxxxxxxxxxx~~ and in drydock)

manent repairs to damaged stem and stem plating as above:
er anchor, as above, repaired without testing.

ommendation

SUBJECT TO margin plate in No.4 hold (s.s.)
being examined and dealt with as necessary
and to indented sheerstrake in way of
frames 3 & 4 (p.s.a) and structure in way etc.
being specially examined and dealt with
as necessary next drydocking and to
bower anchor (repaired 10,62) being tested at
the earliest opportunity, but without other
condition.

Now. Subject
Amended
Without.

S.R.L. APPENDIX.

11 plates F.4, G.7 & 9 (s.s.f), E.8,
and G.8 (p.s.f) slightly indented.
11 plates A.4 (s.s. from aft) slightly set up.

003385-003390-0014

© 2020

Lloyd's Register
Foundation