

COPY

s name "ARISTOLELES"

Port

End:

No. 591

Last survey date 30.10.62.

is subject to For conditions of class see previous endorsement.

. Appendix (as before or none)xx

e of present survey (afloat and in drydock)xx

ent repairs to damaged stem and stem plating as above:
anchor, as above, repaired without testing.

Recommendation

SUBJECT TO margin plate in No.4 hold (s.s.) being examined and dealt with as necessary and to indented sheerstrake in way of frames 3 & 4 (p.s.a) and structure in way etc. being specially examined and dealt with as necessary next drydocking and to bower anchor (repaired 10.62) being tested at the earliest opportunity, but without other condition.

Subject
Amended
Without.

L. APPENDIX.

plates F.4, G.7 & 9 (s.s.f), E.8, and G.8 (p.s.f) slightly indented.
plates A.4 (s.s. from aft) slightly set up.

must be stated above and on the interim certificate.)

Date of Committee

Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation

003385-003390-0018