

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stal S. S. Ghencullen

Report lin

No. 82892

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry

When due _____

❖ 100-A-1. (Stal)

12 1/2 (Stal) Hull Deck

IT 19' 48", FPT 12", APT 21"

BK 6 1/2", ABH, Cen, Plyths A & CP,

Q 85', B 9'

F 23'

Certificate of Classification, to be endorsed "No batten not fitted," and the same to be printed in the Register Book.



© 2021

Michy Affe

Lloyd's Register Foundation

27-10-21

Deck, Angle, Ball Angle, Plate, Tee Ball, or Channel
Angles on upper edge

5	3	3	5	3	3
---	---	---	---	---	---

003409-003416-0022

Bridge Deck Stringer Plate, or gun & thickness

Angle on ditto

2 1/2	2 1/2	2 1/2	2 1/2	2 1/2
-------	-------	-------	-------	-------