

27 SEP 1962

Received from Chief Ship Surveyor.....

P/S NAME "BALLYKNOCK" REPORT BEL. No. 17188  
EA

standing Conditions of Class: SUBJECT to side shell plating etc. (s.s) abreast No.2 hatch and to indented side shell plate D.10 (s.s) being specially examined and dealt with as necessary next drydocking, also to indented keel plate forward being examined and dealt with as necessary by the Special Survey.

L. Appendix. (As before or None)

veys due: SPECIAL SURVEY (D) due 10,62. Proposal to postpone Special Survey approved 9.3.62 period of postponement depending on condition of ship as found at G.E.

ure of Present Survey: (Afloat and in dry dock)

Docking: General Examination as above.  
Wear and tear repairs.  
Permanent repairs to part deferred item as above.

cial Features:

Interim Certificate in order (Yes-~~No-None~~)

ms Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: See Committee Minute.

commendation:


SUBMITTED record of DS 8,62 be assigned, subject to side shell plating etc. (s.s) abreast No.2 hatch and to indented side shell plate D.10 (s.s) being specially examined and dealt with as necessary next drydocking, without other conditions.

DS 8,62 Subject without.

IN S.R.S. APPENDIX

Keel plates Nos 2 & 3 from aft and adjacent 'A' strike plating (s.s) slightly indented.

The Surveyors recommend and it is further submitted postponement of the Special Survey until 8,63 merits approval.



© 2021

Lloyd's Register Foundation

27/9/62