



LLOYD'S REGISTER OF SHIPPING

İSTANBUL BÜROSU

Rıhtım Caddesi, Arzu Han 5/6 Tophane-İstanbul

Telegrams: Lloyd'surv. İstanbul

Telephone: 44.12.86

10th. November 1962

Reference

C. EJB/DET

Dear Sir,

S.S. "HUSEYİN KAPTAN"

I have to confirm that the safety valves of the forward boiler were adjusted under steam when the vessel was under Survey.

Yours faithfully,

for the Surveyors,

G. J. Boulter
G. J. BOULTER.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

003409-003416-0154

A/R

ER

REPORTS

mu

Q 14/11/62



© 2021

Lloyd's Register
Foundation