

"HUSEYIN KAPTAN"

IST 5232.

The Surveyor should be thanked for his letter of the 23rd October, 1962 and should be informed that it would appear that the safety valves of the Forward Boiler also require adjustment under steam and he should state whether this item received attention whilst the vessel was under survey and it is regretted that this item was omitted from the Secretary's letter dated 19th October, 1962.

JW



© 2021

29.10.62.

Lloyd's Register
Foundation

003409-003416-0156