

WILLIAM REARDON SMITH & SONS,
LIMITED.

TELEGRAMS: SMITHCRAFT, CARDIFF.
TELEPHONES: 5116 (4 LINES)

DIRECTORS:

SIR W. REARDON SMITH, BT. DOUGLAS SMITH.
A. J. POPHAM. W. G. LILEY. D. A. LOW.
W. R. REARDON SMITH. A. J. REARDON SMITH.

LB/SN

COLUM BUILDINGS,
MOUNT STUART SQUARE,
CARDIFF

AND AT CREECHURCH HOUSE, LONDON, E. C. 3.

21st February, 1949.
(Monday)

Lloyd's Register of Shipping,
1, Fenchurch Street,
LONDON, E.C. 3.

RECEIVED

22 FEB 1949

AMBU

Dear Sirs,

P. J. C. C. C.

With reference to Certificate issued in connection with
the Special Survey, dated December 1948, it is noted that this Certificate
has been endorsed as follows :-

"The following items relating to the condition of
this ship have been noted, but do not affect the
maintenance of Classification.

Indented Side Shell Plating (Port and Starboard) "

When this vessel was put through Survey at North Shields
all indents on the vessel were removed to the satisfaction of your Newcastle
Surveyor and consequently we do not understand the endorsement which you have
now placed on the Certificate and consider that this should be deleted.

We shall be glad to have your comments regarding this
endorsement.

Yours faithfully,

W. G. Liley
Superintendents' Dept.
(W. G. LILEY)

© 2021

Lloyd's Register
Foundation

003409-003416-0181

Referred to Mr. Perris.

RS

Spl



© 2021

Lloyd's Register
Foundation