

1m. 29.

1

NW B ally km

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "PARKNASILLA"

Report Abn

No. 17181

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2A/6/02.)

Nature of Survey

When due

The attached letter (in reply to an enquiry respecting the fitting of ceiling in the case of another vessel) has now been received from the Aberdeen Surveyors in which it is stated that close ceiling is fitted at the ship's sides in the cargo holds of this steamer.

It is submitted the vessel appears worthy to remain as classed without record of survey.

R.B. Delete "cargo battens not fitted"



© 2021
29.9.33

Lloyd's Register
Foundation

003409-003446-0194