

Ship Surveyor

Received from Chief Ship Surveyor

27 MAY 1948

ME FRANCINE CLORE

REPORT

Lon

No. 116313

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

This vessel holds notations of 100A1 Carrying Petroleum in (Classification contemplated) and "Examined 9,47", with docking date 47.

For outstanding requirements, see previous endorsement.

The LONDON Surveyors report, 3,48, ship examined indrydock, m coated, and minor repairs effected.

The indented bottom plating, as above, examined and found lent meantime. The sternframe wastage examined and found to have ded somewhat. The wastage was cleaned out and sternframe built up W., and a zinc plate fitted in way. The Surveyor recommends this e be specially examined at the next drydocking.

IT IS SUBMITTED this ship is worthy to have her present ls maintained with docking date of 3,48, subject to indented bottom g (p & s.f.) being dealt with at the first convenient opportunity, rnframe (wasted) (E.W. 3,48) being examined at the next drydocking, 30 fathoms of chain cable being supplied at the first opportunity.

on, subject (amended).



© 11 5 21  
— 11 5 48

Lloyd's Register  
Foundation

003409-003416-0785