

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

8th March, 1961.

Classn. (S)

PMW/MAT

Dear Sirs,

Steamer "RUNIC"

This ship was under survey at Melbourne in January/February, when an examination was made of the port main boiler air preheater on account of damage stated to have been sustained by fire.

It is considered that the damaged air preheater of the port main boiler should be specially examined and dealt with as found necessary on the vessel's arrival at a New Zealand port and I shall, therefore, be glad if you will make arrangements for this matter to receive attention as recommended.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Shaw Savill Line Ltd.,
South Side,
Royal Albert Dock,
London, E.16.



© 2021

Lloyd's Register
Foundation

003409-003416-0532