

subject to Evaporator not being used until surveyed.

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

S NAME..... "IRLAND"..... REPORT..... ADN..... No. 3362.....

ABS due 2.62. Commenced 5.62. Surveyor attended to adjust safety valves of Port Boiler but found not satisfactory and survey not advanced.

IT IS SUBMITTED that this vessel WILL BE eligible for the record ABS 5.62 on completion, subject as above.

TO COMPLETE ABS.

Both Exhaust Gas Economisers remain to be examined in their entirety, all safety valves to be adjusted except in the Starboard Boiler and the oil burning arrangements and remote controls to be examined working.



© 2020


Lloyd's Register
 Foundation