


TELEPHONE 3-7506

LLOYD'S REGISTER OF SHIPPING

36 FURNESS WITHY BUILDING,

HALIFAX, N. S.,



March 13th, 1945.

The Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street,
London E.C.3.

Dear Sir:

We are in receipt of your letter (S) of the 9th ultimo respecting our Rpt. 5061 "M.M.S. 1055". We are today in receipt of a letter from our Surveyor at Meteghan stating the number of ordinary deck beams is 35, with an average spacing of 33". There are 4 strong beams with a spacing of 12'. The shifts of the first and second futtocks are 36". The windlass and steering arrangements were tried under working conditions and found efficient. Mr. Berthe' regrets having omitted the above items when making out his Report. It is noted that a period of nine years has been assigned to the class of these vessels and will be guided accordingly in the case of the remaining vessels.

We are, Dear Sir,

Yours faithfully,

Surveyor.



© 2020

Lloyd's Register
Foundation

003434-003443-0206

m

H
R J

6 APR 1945

the Surveyor should be requested to reply to the enquiry respecting the length of the keel scapula as per endorsement - 6.2.45

J.C.D.
6.4.45

Class C L5 to
d/fsc: - 10/4



© 2020

Lloyd's Register
Foundation