

12 OCT 1953

Received from Chief Ship Surveyor

JD. SHIP'S NAME "KYLEQUEEN" REPORT Nwc. No. 110765

Outstanding Conditions of Class: Subject to indented bulwark plating, etc. (p.s.) abreast No.1 hatch being dealt with by the Special Survey and to Permanent repairs to W.T. door on aft bulkhead of No.2 hold and indented (and holed) shell plate No.3 in 4th strake below sheer (s.s.) and to indented shell plates, etc. (p.s.) in way of No.4 hold being specially examined and dealt with as necessary next drydocking, also 15 fathoms of chain cable being supplied at the earliest opportunity. ACTION is Endorsement of Class (B) (As before ~~xxxxxx~~) DEFERRED for Special Survey by 3,53.

Surveys due: SPECIAL SURVEY (C) due 1,53 - postponement until end of 3,53 approved. (See letter dated 19.2.53). Further postponement approved. (See letter dated 24.4.53.)

Nature of Present Survey: (Afloat and in dry dock)

Special Survey. Alterations.

Special Features:

Is Interim Certificate in order (Yes, No - None) ~~xxxx~~

Items Outstanding: (If any for S.S. or A.S.)

NONE

S.S. ~~xxxx~~ completed by: 15.9.53.

Recommendation:

SUBMITTED that record of docking 9,53 and notation of "ss.Shl.9,53" be assigned, without special conditions.

9,53 Shl. ) Without.  
ss.Shl.9,53.)

DELETE ENDORSEMENT OF CLASS (B).

The Certificate of Classification to be endorsed "Cargo Batches not fitted" and the same notation to be printed in the Register Book.

EL 6.10.53

Lloyd's Register Foundation

003434-003443-0309