

16 JUL 1959

Received from Chief Ship Surveyor

SHIP NAME "KYLOE" REPORT Sld. No. 37174
GB

standing Conditions of Class: SUBJECT to set in and indented side
shaft plates E.9, F.9, G.8 & 9 (p.s. from fwd) and H.2 & 3, J.2
(s.s. from fwd) being dealt with as necessary next S.S.

L. — Appendix. (As before ~~or None~~)

Location of Present Survey: (~~At sea and~~ in dry dock)

Examination of set up bottom shell etc. on account of damage due to
foul berth.

Recommendation:

SUBJECT as above, and to set up bottom shell
etc. being repaired and hydraulically tested
before the ship proceeds to sea.

As Now. Subject

IN S.R.L. APPENDIX

Forecastle rising plate etc.(p.s.) set in.
G.3 (p.s.f) indented.

NOTE:- The ship is now laid up at Sunderland.

© 2020



Lloyd's Register
Foundation

003434-003443-0333