

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

30 APR 1958

SHIP'S NAME.....

"SUNFLEET"

REPORT.....

Sou No 24784.

Damage to boiler through failure of a boiler tube.
 Boiler tubes examined as far as practicable and found generally
 wasted. One tube renewed and one tube fitted with a stopper.
 Repairs examined on completion and boiler found in order and
 the Surveyor recommends all pitted and wasted plain boiler
 tubes being renewed on the vessel's arrival at a North East Coast
 port direct from Portsmouth.

IT IS SUBMITTED that this vessel is eligible to remain
 AS CLASSED, subject as recommended.



© 2021

ADM

28 APR 1958

U.S. Lines

Blue Bell Reports

Lloyd's Register
Foundation

003450-003457-0017

ertifi
hile t
ood tl