

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor..... 25 FEB 1958

SHIP'S NAME..... "SUNFLEET"..... REPORT..... Ant..... No.33213.

Damage stated due to propeller striking the quay.

Screwshaft examined in lathe, found in order and re-fitted with a spare propeller.

IT IS SUBMITTED that this vessel is eligible for THE RECORD, TS CL 1.58.



© 2021

21.2.58.

Lloyd's Register
Foundation

003450-003451-0026