

THROUGH HONG KONG  
COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

28th January, 1958

Dear Sirs,

(S) Steamer "TRIBEAM"

This ship was under survey at Shimonoseki last month when the complement of equipment on board was found to be deficient of a bower anchor.

The class of the ship has been continued subject to a bower anchor being supplied and enlarged end links being fitted to the starboard chain cable as considered necessary at the earliest opportunity.

Please let me know what arrangements you propose to make in this respect.


A record of Drydocking 12,57 and notation of Boiler Survey 12,57 have been assigned.

Yours faithfully,

c.c. H.Kg.

Assistant Clerk to the  
Classification Committee

Messrs. Wheelock, Marden & Co. Ltd.,  
701-707 Edinburgh House,  
Queen's Road Central (Postbox 85),  
HONG KONG



© 2020

Lloyd's Register  
Foundation

003458-003465-0127