

S. NAIROBI  
STERN FR

8718

© 2020

Lloyd's Register  
Foundation

M.S. STANVAC NAIROBI

Finished repair by welding cracked section of  
stern frame top, stb'd side.

Aug. 18, 1958

SS/MS "

TO ACCOUNT

Rpt. No .....

Kohle Rpt. J. No 6065

Dated .....

SUBJECT:-



© 2020

Lloyd's Register  
Foundation

003458-003465-0288