

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

Your ref. WJHP/JB
 LLOYDS

24th May 1962.

Dear Sirs,

M.S. "ETTRICKBANK"

R I acknowledge your letter of the 23rd May, and would inform you that this vessel's class is subject to indented side shell plates J.8 H.8 and G.6 (p.s. from aft) indented bottom shell plates S.15 & 16, B.15 & 16, C.16 (s.s. from aft), also upper deck plating (p.s.) and forward bulkhead of deep tank (p.s.) (fire damage) being specially examined and dealt with as necessary by the Special Survey, to permanent repairs to side shell plates H.9 & 10 (p.s. from aft) also to indented shell plates G.12 and H.13 (p.s.) being specially examined, next drydocking.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Andrew Weir & Co. Ltd.,
Baltic Exchange Buildings,
21 Bury Street,
LONDON E.C.3



© 2020

Lloyd's Register
Foundation

003467-003473-0029