

30 SEP 1960

Received from Chief Ship Surveyor.....

SHIP'S NAME "STATE OF WEST BENGAL" REPORT Cal. No. 19724.

Outstanding Conditions of Class: SUBJECT to Nos.1 & 2 keel plates and adjacent garboard strake (p.s.f) indented shell plating in way of after end of port deep tank and to bottom shell plates A.9 & 10, B.6 & 7 (p.s from aft), also fore peak bulkhead locally wasted in way of port chain locker being examined and dealt with as necessary, and to (holed and leaky) No.1 D.B. tank top plating etc. being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (As before ~~xxxxxxx~~)

Surveys due: SPECIAL SURVEY (C) due 10,60. Postponement until 4,61 approved 14,6,60 provided a satisfactory G.E. is held.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Commencement of General Examination.
Wear and tear repairs including part deferred items as above.

Special Features:

Is Interim Certificate in order (Yes ~~No None~~)

Items Outstanding: (If any for S.S.) ALL ITEMS.

TO COMPLETE G.E.:- Selected D.B. tanks to be examined.

S.S. to be completed by:

Recommendation:

SUBMITTED record of DS 8,60 be assigned, subject to Nos.1 & 2 keel plates and adjacent plating in way of after end of port deep tank, also to (holed and leaky) No.1 D.B. tank top plating etc. being specially examined and dealt with as necessary next drydocking, without other conditions.

DS 8,60 Subject
Without.

IN S.R.L. APPENDIX.
Tunnel plating slightly indented.

Attchd
22/9/60

G.E. PART HELD.

© 2020



Lloyd's Register
Foundation