

101
.4
yes

name "ADELFOTIS II" Survey port Rka. No. 1477
Last survey date 26.4.62
is subject to :

the propeller and tailshaft cone
being specially examined at the
next dry docking.

~~of present survey~~

Docking. Screwshaft examined.

Sternbush re-wooded.

~~repairs~~

One bronze propeller blade found
slightly bent at tip and cracked on astern
edge. Blade now faired and crack welded.


endation

IT IS SUBMITTED that this vessel
is eligible to remain as classed with fresh
record of TS (CL) 4.62 now, without special
condition.

003474-003478-0106

~~complete surveys partly held~~

NOTE: The Rka. Surveyor should be asked to
confirm that at this Survey the screw-
shaft cone was found in good order in view of no
statement to this effect having been made in the body
of his Report.



© 2020 5.8.62

*Confirmed
Rka 12/16/62*

Lloyd's Register
Foundation

been
li
of