

s.s. "PLAVNIK".

Survey for Classification.  
-----

The Trieste Surveyors state the Owners have no records of the electrical equipment.

IT IS SUBMITTED the Surveyors be asked to state the number and kilowatt rating of the dynamos, the voltage for lighting and power and to state what essential power services, if any, are electrically driven.

Susak Rpt.798 states briefly that the electrical fittings were generally examined and it is concluded this examination included the cables and that they are in accordance with Rule requirements and that the fuses were examined. This should be confirmed.

*Row*

13th October, 1938.

18/10



© 2020

Lloyd's Register  
Foundation

003474-003478-0233

Handwritten mark resembling a stylized 'E' or '3'.

1300 ... 1820

Handwritten signature or initials.

Handwritten text at the bottom of the page.



© 2020

Lloyd's Register Foundation



Vertical text on the right edge of the page.